Time Bowl Rinse Relay

12.0913.00



- . For Cascade cuspidor
- · 3/8" female Poly-Flo
- 1/8" barb
- · 3/8" x 1/4" barb

- · For filter regulator manifolds and Excellence cuspidor
- · 1/8" and 1/4" barb

Relay

· 9-hole gasket, 24.0137.01 (10)

Relay Valve with Holdback

Time Delay Relay

42.0534.00

34.0043.00



- · For tooth dryer
- · Non-Cascade
- 1/8" barbs (1)
- . 1/4" barbs (2)

Cup Fill Relay and Cup Fill Timer Stabilizer Kit

12.0934.00 Cup fill relay 90.0456.00 Stabilizer kit

- . For Cascade cup fill





NOTE: Kit replaces the cup fill timer and improved flow adjustment.

Service Tip

Air bubbles in the water or sputtering may be caused by:

- · Loose syringe handle
- . Defective O-ring on the connector tube at the syringe terminal
- · Leaking diaphragm in the water regulator
- · Leaking diaphragm in any water relay valve